

**Work Order Details**

Work Order ID	WKORD000059
Work Order Type	Corrective Maintenance
Work Order Deadline	2022-05-27 14:30:00 (GMT+0800)
Customer	Irctc
Requested Date & Time	2022-05-20 18:41:28 (GMT+0800)
Completion Date & Time	2022-05-20 19:06:07 (GMT+0800)
Customer Address	Bilaspur Railway Station Sub Post office, Station Road, Railway Colony, Bilaspur, Chhattisgarh, India

**All Tasks Details**

Task ID	Task Type	Start Date & Time	End Date & Time
TSK000230	RCD Compliance	2022-05-20 18:46:53 (GMT+0800)	2022-05-20 19:06:07 (GMT+0800)

**Task Details - TSK000230**

Task Type	RCD Compliance
Assignees	Ashu
Start Date & Time	2022-05-20 18:46:53 (GMT+0800)
End Date & Time	2022-05-20 19:06:07 (GMT+0800)
Customer Site	Irctc PO
Customer Site Address	Bilaspur Railway Station Sub Post office, Station Road, Railway Colony, Bilaspur, Chhattisgarh, India
Updated Site Address	34CW+43V, Nagdouna Colony, Talapara, Bilaspur, Chhattisgarh 495004, India
Notes	RCD-T1


**Task Results Overview**

Submitted On	Assignee	Services Delivered
2022-05-20 18:51:44 (GMT+0800)	Ashu	-



**RCD Compliance Checklist**



Inspection Details	Inspection start
--------------------	------------------


**RCD Compliance Checklist : General**

What type of inspection?	Switchboard mounted RCD
Photo of switchboard.	<div data-bbox="858 479 1145 981" style="text-align: center;">  </div> <p data-bbox="938 1003 1072 1034" style="text-align: center;"><b>Comments</b></p> <p data-bbox="979 1061 1031 1093" style="text-align: center;">Test</p>
Is there information indicating test date on or next to the switchboard or portable equipment?	Yes
List last known test date	2022-05-20 18:47:32 (GMT+0800)
Are the test dates in the correct range?	Yes
Description of old test dates if any	Test
Have all documents relating to the testing been completed?	Yes
Date of last test	2022-05-20 18:47:38 (GMT+0800)

**RCD Compliance Checklist : Switchboard Mounted RCDs**

<p>Is inspection of switchboard mounted RCD?</p>	<p>Yes</p>
<p>Numbers of switchboards</p>	<p>2</p>
<p>Are the RCD's in good order?</p>	<p>Yes</p>
<p>Photo of damage</p>	 <p><b>Comments</b></p> <p>Test</p>
<p>Photo of RCD</p>	 <p><b>Comments</b></p> <p>Test</p>
<p>Are RCD's installed on all required circuits?</p>	<p>No</p>

<p>Photo of circuit requiring RCD</p>	 <p><b>Comments</b></p> <p>Test</p>
<p>Any evidence of wear and tear or hot spots?</p>	<p>At Risk</p>
<p>Photo of damage</p>	 <p><b>Comments</b></p> <p>Test</p>
<p>Are any of the RCD's on a banned list (check the list from ESV)?</p>	<p>Complaint</p>

<p>Photo of RCD</p>	 <p><b>Comments</b></p> <p>Test</p>
<p>Has the RCD been tested?</p>	<p>Yes</p>
<p>Test date</p>	<p>2022-05-20 18:47:27 (GMT+0800)</p>
<p>Company</p>	<p>Zinier</p>



**RCD Compliance Checklist : Power Point with Built in RCD**

Are there any built in RCD power points?	Yes
Has the Power point RCD been Tested?	Yes
Circuit Number	1245
Photo of Power Point	<div data-bbox="863 667 1150 1167" data-label="Image"> </div> <p data-bbox="938 1189 1070 1218"><b>Comments</b></p> <p data-bbox="983 1249 1026 1279">GST</p>
Photo of Power Point	<div data-bbox="863 1335 1150 1834" data-label="Image"> </div> <p data-bbox="938 1856 1070 1886"><b>Comments</b></p> <p data-bbox="983 1917 1026 1946">Test</p>



**RCD Compliance Checklist : Portable RCD**


<p>Are portable RCDs being inspected?</p>	<p>Yes</p>
<p>Is the equipment in good condition? (no damage broken/parts)</p>	<p>Pass</p>
<p>Photo of defect</p>	<div data-bbox="863 573 1150 1070" data-label="Image"> </div> <p><b>Comments</b></p> <p>Test</p>
<p>Photo of defect</p>	<div data-bbox="863 1245 1150 1742" data-label="Image"> </div> <p><b>Comments</b></p> <p>Test</p>
<p>Are push buttons on portable RCD's being tested before use? (located on generators, PSOA)</p>	<p>Yes</p>
<p>Details of response.</p>	<p>Test</p>

<p>Has the plant equipment log book been filled in (if applicable)?</p>	<p>Yes</p>
<p>Photo of equipment log</p>	 <p><b>Comments</b></p> <p>Test</p>
<p>Photo of equipment log</p>	 <p><b>Comments</b></p> <p>Test</p>
<p>Details of last entry.</p>	<p>Test</p>

**RCD Compliance Checklist : Completion**

Does the Inspection Pass?	Fail
List reason for Fail.	Test
Recommendations	Test
Date of Inspection	2022-05-20 18:50:21 (GMT+0800)
Position.	Electrical Supervisor

## Customer Signature



Approved By  
Ashu

Signed On  
2022-05-20 18:51:44 (GMT+0800)